



## KBM 50-2

Sr.No.	Part Name	Part no.	Qty.
1	Main Body	210101	1
2	Guide Strip 8mm	210311	1
3	Guide Strip 12mm	210310	2
4	Gib	210501	1
5	SHC Grub Screw M5 x 20 _ Round End	211701	4
6	Lock nut M5	101760100	4
7	Guide Plate machining	120173100	1
8	Rack	120209100	1
9	SCH Screw M5 X 25	121763100	2
10	Int.tooth lock washer M5	101739100	2
11	Spindle	210202	1
12	Spindle bush	210203	2
13	Spindle Lock countersunk screw M6 x 16	211705	1
14	Spindle cap	210217	1
15	Handle lever SA	219902	3
16	Base SA	129947100	1
17	SHC Screw M8 x 25	101712100	2
18	Tooth Lock Washer M8	101736100	4
19	Cord Clamp	210406	1
20	SH screw M4 x 8	121761100	10
21	Spiral Gland	109909102	1
22	Fuse CE 8 amp	211351	1
23	Switch Plate	212001	1
24	Main Switch	101302100	1
25	Power protection switch	101320100	1
26	Cable conduit	211306	0.3 Mtr.
27	Gland PG9	211309	2
28	Coolant bottle	210405	1
29	Spec.plate	121495100	1
30	NRB Bracket Machining	120187100	1
31	NRB HK3516	120903100	1
32	SH Screw M6 X 40	121770100	2
33	Plain washer M6	101709100	2
34	Key	210215	1
35	Drill Unit	129979100	1
36	SH Screw M6 X 30	101750100	4
37	Side Cap	120410100	1
38	PH SELF TAP 4.8X19 (80201279)	121774100	4
39	SH Grub screw M10 x 8	101744100	2
40	Lock foil	210301	1
41	SH M3X10 *	231704	2
42	Belt clamp SA *	219911	1
43	SHC Screw M8 x 20	101708100	2
44	Main body gasket	210318	1
45	3 PIN 16AMP POWER CORD CE-1SQMM X3CORE X 3.1 MTR *	721301	1

\* PARTS NOT SHOWN IN FIG.

PART NO.

121498100

REV:

4